

Display Crosslist for LED Converter



Manufacturer	Size (inch)	Display Name	Spec dated	LED Converter	Adapter cable #
Admatec		NLC800T70L480CTM	unknown	internal control!	
Ampire	4,0	AM-480272A	26. Sep. 05	TBD	
Ampire	5,0	AM800480LTMQW-00H-1	2. Jul. 09	TBD	
Ampire	8,0	AM-800600C1TMQW-00H	25. Jul. 07	PS-LD0101-x-180	10
Ares	17,0	ED170S01	2. Mrz. 10	TBD	
AUO	4,0	A040CN01	12. Jul. 05	PS-LD0602-x-020	
AUO	5,7	G057QN01	20. Nov. 07	PS-LD0602-x-015	1
AUO	5,7	G057QN01	4. Okt. 07	PS-LD0602-x-015	1
AUO	5,7	G057VN01 V0	9. Nov. 07	PS-LD0602-004	1
AUO	6,5	G065VN01 V2	23. Apr. 09	internal control!	
AUO	7,0	C070VW02	11. Mai. 06	PS-LD0101-x-150	
AUO	7,0	G070VW01 V0	15. Mai. 09	internal control!	
AUO	8,4	G084SN05 V8	23. Mrz. 09	internal control!	
AUO	10,4	G104SN01 V1	11. Feb. 09	internal control!	
AUO	10,4	G104SN02 V2	11. Feb. 09	internal control!	
AUO	12,1	G121SN01 V4	11. Feb. 09	internal control!	
AUO	12,1	B121EW04 V1	12. Okt. 07	internal control!	-
AUO	15,0	G150XG01 V2	19. Nov. 08	PS-LD0301-031	3 / 6
AUO	15,0	G150XG01 V3	3. Jun. 10	internal control!	
AUO	15,4	B154PW04 V2	10. Jul. 08	TBD	
AUO	15,4	B154EW09	18. Jul. 08	TBD	
AUO	19,0	M190PW01 V8	15. Nov. 10	TBD	
AUO	24,0	M240HW01 V1	11. Mrz. 10	TBD	
AUO	24,0	M240HW01 V6	16. Jul. 09	PS-LD0801-01*	
BiSearch	12,1	ELB121S03-TL01-THA	11. Feb. 08	TBD	
Casio	5,7	COM57H5137XSC	3. Apr. 09	internal control!	
CCT	7,0	T4880C03WP01	2. Aug. 07	PS-LD0101-x-180	
CPT	15,4	CLAA154WB11A	29. Mai. 09	PS-LD0602-x-020	
CMO	7,0	G070Y2-L01	24. Jul. 09	internal control!	
CMO	7,0	G070Y3-T01	23. Dez. 07	PS-LD0602-x-020	
CMO	7,0	LW700AT9309	9. Mrz. 09	PS-LD0101-1-160	10
CMO	8,0	G080Y1-T01	11. Nov. 09	PS-LD0101-x-120	10
CMO	10,4	G104X1-L04	4. Jan. 10	internal control!	
CMO	12,1	G121X1-L01	14. Jan. 09	TBD	
CMO	15,6	M156B3-LA1	15. Jul. 10	PS-LD0801-01*	
CMO	18,5	M185B3-L01	2. Jul. 09	TBD	
CMO	18,5	M185B3-LA1	9. Mrz. 10	PS-LD0801-01*	
CMO	18,5	M185BGE-L22	10. Mai. 11	PS-LD0401-x-065	
CMO	19,0	M190Z3-L02	21. Jul. 08	internal control!	
CMO	21,5	M215H3-LA1	21. Mrz. 10	TBD	
CMO	21,5	M215H3-L01	24. Sep. 09	2xPS-LD0602-x-020	
CMO	22,0	M220Z3-L07	13. Mai. 09	2xPS-LD0602-x-020	
CMO	22,0	M220Z3-LA1	6. Jan. 10	PS-LD0801-01*	
Data Image	7,0	FG0700G3DSSWBG01	11. Sep. 08	PS-LD0101-x-180	
Data Image	8,0	FG080036DSSWBG01	30. Jun. 08	PS-LD0101-x-200	10
Emerging Disp	3,5	ET035009DM6	22. Jun. 07	PS-LD0602-x-020	
Emerging Disp	4,3	ET043000DM6	18. Sep. 07	PS-LD0602-x-018	
Emerging Disp	5,7	ET057000DM6	26. Sep. 06	PS-LD0101-x-040	
Epson	8,0	L5F30978T	9. Jan. 09	TBD	
Epson	8,0	L5S30978	1. Jul. 09	PS-LD0801-01*	

Evervision	3,5	VGG322419-6UFLWA	16. Nov. 07	PS-LD0602-x-020	
Evervision	3,5	VGG322423-6UFLWA	26. Dez. 07	PS-LD0602-x-020	
Evervision	3,5	VGG322425-6UFLWA	27. Mai. 08	PS-LD0101-x-040	
Evervision	3,5	VGG322427-6UFLWA	27. Mai. 08	PS-LD0101-x-040	
Evervision	4,3	VGG482707-6UFLWC	6. Okt. 08	PS-LD0602-x-020	
Evervision	4,3	VGG482707-6UFLWD	6. Okt. 08	PS-LD0602-x-020	
Evervision	4,3	VGG482704-6UFLWD	14. Aug. 07	PS-LD0602-x-020	
Evervision	4,3	VGG482704-6UFLWC	20. Dez. 07	PS-LD0602-x-020	
Evervision	4,3	VGG482704-6UFLWF	25. Jan. 08	PS-LD0602-x-020	
Evervision	4,3	VGG482704-6UFLWE	19. Dez. 07	PS-LD0602-x-020	
Evervision	4,3	VGG482711-6UFLWA	30. Apr. 10	PS-LD0602-x-020	
Evervision	5,7	VGG322403-7UFLWA	5. Mai. 08	PS-LD0101-x-060	10
Evervision	5,7	VGG322403-7UFLWB	24. Sep. 08	PS-LD0101-x-060	10
Evervision	5,7	VGG322403-7UFLWE	5. Dez. 07	PS-LD0101-x-060	10
Evervision	5,7	VGG322403-7UFLWF	24. Sep. 08	PS-LD0101-x-060	10
Evervision	5,7	VGG322426-7UFLWA	4. Jun. 08	PS-LD0101-x-200	10
Evervision	5,7	VGG322426-7UFLWB	4. Jun. 08	PS-LD0101-x-200	10
Evervision	5,7	VGG322404-6UFLWA	22. Aug. 07	PS-LD0101-x-060	10
Evervision	5,7	VGG322404-6UFLWB	19. Dez. 07	PS-LD0101-x-060	10
Evervision	5,7	VGG644803-6UFLWA	13. Aug. 07	PS-LD0101-x-140	10
Evervision	5,7	VGG644803-6UFLWB	13. Aug. 07	PS-LD0101-x-140	10
Evervision	5,7	VGG644803-6UFLWE	12. Mrz. 08	PS-LD0101-x-140	10
Evervision	5,7	VGG644803-6UFLWF	21. Mrz. 08	PS-LD0101-x-140	10
Evervision	5,7	VGG644804-6UFLWA	5. Aug. 08	PS-LD0101-x-200	10
Evervision	5,7	VGG644804-6UFLWB	5. Aug. 08	PS-LD0101-x-200	10
Evervision	7,0	VGG804805-6UFLWA	13. Aug. 07	PS-LD0101-x-200	10
Evervision	7,0	VGG804805-6UFLWC	5. Dez. 07	PS-LD0101-x-200	10
Evervision	7,0	VGG804805-6UFLWD	30. Jan. 08	PS-LD0101-x-200	10
Evervision	7,0	VGG804805-6UFLWE	5. Jun. 08	PS-LD0101-x-200	10
Evervision	7,0	VGG804806-6UFLWA	21. Mai. 08	PS-LD0101-x-200	10
Evervision	7,0	VGG804806-6UFLWB	21. Mai. 08	PS-LD0101-x-200	10
Evervision	7,0	VGG804806-6UFLWC	21. Mai. 08	PS-LD0101-x-200	10
Evervision	7,0	VGG804806-6UFLWD	21. Mai. 08	PS-LD0101-x-200	10
Hitachi	4,7	SP12Q01L6ALZZ	12. Mai. 06	voltage driven!	-
Hitachi	5,1	SP14N01L6VLCZ	25. Mrz. 10	PS-LD0101-x-080	-
Hitachi	5,7	SP14Q003-A	9. Mrz. 06	voltage driven!	-
Hitachi	5,7	SP14Q006	4. Jul. 04	voltage driven!	-
Hitachi	5,7	SP14Q011-A-2	12. Feb. 07	voltage driven!	-
Hitachi	5,7	SX14Q009	1. Sep. 06	voltage driven!	-
Hitachi	5,7	TX14D12VM1CBC	9. Mrz. 07	voltage driven!	-
Hitachi	5,7	TX14D12VM1CPC	27. Jul. 07	voltage driven!	-
Hitachi	5,7	TX14D14VM1CAB	31. Aug. 07	voltage driven!	-
Hitachi	5,7	TX14D12VM1CPC	13. Mai. 08	PS-LD0602-x-021 (5V)	
Hitachi	5,7	TX14D16VM1CPC	9. Jan. 09	PS-LD0101-x-080	
Hitachi	5,7	TX14D22VM1BAA	20. Okt. 09	PS-LD0602-x-010 (5V)	-
Hitachi	5,7	TX14D22VM1BPA	19. Nov. 09	PS-LD0602-x-010 (5V)	-
Hitachi	6,2	TX16D11VM2CAC	31. Okt. 08	PS-LD0602-x-021 (5V)	
Hitachi	8,0	TX20D19VM2BAA	7. Aug. 08	PS-LD0602-x-030 (5V)	-
Hitachi	8,0	TX20D26VM0AAA-1	18. Mai. 09	PS-LD0401-1-100	-
Hitachi	8,0	TX20D26VM0APA	22. Jun. 09	PS-LD0401-1-100	-
Innolux	10,2	AT102TN43	14. Aug. 08	internal control!	-
JNM	8,4	G084SN03 V1	7. Apr. 10	TBD	
JNM	10,4	G104X1-L01	17. Mai. 10	TBD	
Kyocera	4,7	KCG047QVLAB-A21		voltage driven!	-
Kyocera	4,7	KCG047QVLAE-A21		voltage driven!	-
Kyocera	4,7	KHG047QVLAB-G00		voltage driven!	-

Kyocera	5,7	KCG057QVLDG-G00	13. Mrz. 07	PS-LD0602-x-025	1
Kyocera	5,7	KCG057QVLDG-G77	23. Mai. 06	PS-LD0602-x-025	1
Kyocera	5,7	KCG057QVLDK-G00	10. Mrz. 07	voltage driven!	-
Kyocera	5,7	KCG057QVLEC-G00	24. Dez. 08	TBD	
Kyocera	5,7	KG057QVLCD-G00	13. Mrz. 07	PS-LD0602-x-025	1
Kyocera	5,7	KG057QVLCE-G00	7. Jun. 06	PS-LD0602-x-025	1
Kyocera	5,7	KG057QVLCF-G00	10. Mrz. 07	voltage driven!	-
Kyocera	5,7	TCG057QVLAC-G00	8. Feb. 06	PS-LD0602-x-025	1
Kyocera	5,7	TCG057QVLAC-G01	10. Mrz. 07	PS-LD0602-x-025	1
Kyocera	5,7	TCG057QVLAD-G01	18. Apr. 07	PS-LD0602-x-025	1
Kyocera	5,7	TCG057QVLAF-G01	1. Mrz. 07	voltage driven!	-
Kyocera	5,7	TCG057QVLBA-G00	12. Dez. 07	PS-LD0602-x-015	-
Kyocera	5,7	TCG057VGLAC-G00	19. Okt. 06	PS-LD0602-x-025	1
Kyocera	5,7	TCG057VGLAD-G00	14. Jun. 06	PS-LD0602-x-025	1
Kyocera	5,7	TCG057VGLAE-G00	10. Mrz. 07	voltage driven!	-
Kyocera	5,7	TCG057VGLBA-G00	12. Dez. 07	PS-LD0602-x-015	-
Kyocera	5,7	TCG057VGLCA-G00	12. Aug. 09	PS-LD0602-x-025	1
Kyocera	5,7	TCG057VGLCS-H50	25. Nov. 09	PS-LD0301-028-B	
Kyocera	5,7	THG057VGLAC-H00	17. Apr. 07	PS-LD0602-x-025	1
Kyocera	5,7	TCG057QVLC A-G00	19. Feb. 09	PS-LD0602-x-025	1
Kyocera	6,2	KHG062HVLAK-G00	17. Feb. 07	PS-LD0602-x-015	-
Kyocera	7,0	TCG070WVLP	8. Nov. 10		
Kyocera	7,5	KCG075VGLBJ-G00	16. Apr. 07	PS-LD0602-x-025	2
Kyocera	7,5	TCG075VGLAE-G00	13. Apr. 07	PS-LD0602-x-025	2
Kyocera	7,5	TCG075VGLEAANN-GN00	25. Mrz. 11	PS-LPL0801-060	
LG	18,5	LC185EXN-SCA1	22. Jan. 10	internal control!	
LG	21,5	LM215WF3-SDA1	27. Apr. 10	TBD	
LG	21,5	LM215WF3-SLA1	27. Aug. 09	TBD	
LG	21,5	LM215WF3-SLC1	30. Sep. 10	PS-LD0401-x-110	
LG	21,5	LM215WF4-TLA1	14. Dez. 09	TBD	
LG	23,0	LM230WF3-SLB1	31. Mrz. 10	PS-LD0401-x-110	
LG	23,0	LM230WF5	15. Dez. 09	TBD	
LG	27,0	LM270WQ1-SDA2	16. Sep. 09	PS-LD0608-01	
Litemax	10,4	SP1075E	26. Jun. 08	TBD	
Microtips	5,7	MTF-T057AMSLN-V1	13. Apr. 07	PS-LD0101-x-270	10
Mitsubishi	4,3	AA043MA01	8. Feb. 08	PS-LD0602-x-015	
Mitsubishi	5,0	AA050ME01	9. Dez. 08	PS-LD0602-x-015	
Mitsubishi	5,0	AA050MG01	7. Jul. 10	PS-LD0602-x-015	
Mitsubishi	6,5	AA065VD01	16. Jun. 09	PS-LD0301-038	14
Mitsubishi	8,4	AA084SB01	4. Mrz. 09	PS-LD0301-029	14
Mitsubishi	9,0	AA090ME01	16. Jun. 09	PS-LD0301-032	14
Mitsubishi	10,4	AA104VH02	26. Mai. 09	PS-LD0301-029	14
Mitsubishi	10,4	AA104XD02	14. Jul. 09	PS-LD0301-029	14
Mitsubishi	12,1	AA121SM02	25. Jun. 09	PS-LD0301-032	14
Mitsubishi	12,1	AA121TD01	22. Dez. 09	internal control!	
Mitsubishi	12,1	AA121XK02	19. Okt. 09	PS-LD0301-032	14
Mitsubishi	14,1	AA141TC01	24. Jun. 10	TBD	19
Mitsubishi	15,0	AA150XT01	9. Jun. 09	PS-LD0401-x-110	17
Mitsubishi	15,0	AA150XT11	9. Jun. 09	2xPS-LD0401-x-100	17
Mitsubishi	15,0	AA150XS11	20. Apr. 09	TBD	
Mitsubishi	19,0	AA190EA01	15. Jun. 11	2xPS-LD0401-x-130	17
NEC	5,7	NL6448BC18-01	1. Jun. 08	PS-LD0602-x-025	11
NEC	5,7	NL6448BC18-01F	1. Jul. 08	PS-LD0602-x-025	
NEC	5,7	NL6448BC18-07	1. Feb. 11	PS-LD0602-x-015	
NEC	6,5	NL10276BC13-01C	1. Feb. 08	PS-LD0602-x-015	4
NEC	6,5	NL10276BC13-01C	1. Aug. 06	PS-LD0602-x-016	4

NEC	6,5	NL6448BC20-21C	1. Dez. 07	PS-LD0602-x-010	4
NEC	6,5	NL6448BC20-21D	1. Jul. 07	PS-LD0602-x-010	4
NEC	7,0	NL8048BC19-02	1.Mar.08	PS-LD0602-x-025	5
NEC	7,0	NL8060BC19-08	mündlich	PS-LD0801-01*	
NEC	7,2	NL8060BH18-02	1. Mai. 11	PS-LD0602-x-020	
NEC	8,4	NL8060BC21-11	1. Aug. 10	TBD	
NEC	8,4	NL8060BC21-11C	1. Jan. 10	PS-LD0801-01*	
NEC	8,4	NL8060BC21-11D	1. Jan. 10	PS-LD0801-01*	
NEC	8,4	NL6448BC26-22F	1. Jun. 08	PS-LD0602-x-025	11
NEC	8,4	NL6448BC26-26	1. Jan. 09	PS-LD0801-01*	
NEC	8,4	NL6448BC26-20F	1. Jun. 08	PS-LD0602-x-025	11
NEC	8,4	NL668BC26-27C	1. Jan. 09	PS-LD0801-01*	
NEC	8,9	NL10260BC19-01D	1. Jun. 08	PS-LD0602-x-015	-
NEC	8,9	NL12876BC15-01	1. Apr. 08	PS-LD0801-01*	-
NEC	9,0	NL8048BC24-06	1. Nov. 08	PS-LD0801-01*	
NEC	9,0	NL8048BC24-09D	1. Mrz. 10	PS-LD0801-01*	
NEC	10,4	NL8060BC26-35C	1. Dez. 08	PS-LD0801-01*	
NEC	10,4	NL8060BC26-35D	1. Dez. 08	PS-LD0801-01*	
NEC	10,4	NL6448BC33-70C	1. Dez. 08	PS-LD0801-01*	
NEC	10,4	NL6448BC33-70D	1. Jan. 10	PS-LD0801-01*	
NEC	10,4	NL6448BC33-70F	1. Okt. 09	PS-LD0801-01*	
NEC	10,4	NL6448BC33-71D	mündlich	PS-LD0801-01*	
NEC	10,4	NL10276BC20-10	1. Mai. 10	TBD	
NEC	10,4	NL10276BC20-18	1. Feb. 09	PS-LD0801-01*	
NEC	12,1	NL10276BC24-14	1. Okt. 06	PS-LD0602-x-020	
NEC	12,1	NL10276BC24-19D	1. Jul. 09	PS-LD0602-x-020	
NEC	12,1	NL10276BC24-19D	1. Aug. 07	PS-LD0602-x-020	
NEC	12,1	NL8060BC31-47D	1. Jul. 09	PS-LD0602-x-025	
NEC	12,1	NL12880BC20-05D	1. Feb. 11	PS-LD0801-01*	
NEC	15,0	NL10276BC30-34D	1. Mai. 09	PS-LD0605-02	
Optrex	3,0	T-55149GD030J-MLW-AJN	28. Mrz. 08	PS-LD0101-x-030	
Optrex	3,5	T-51963GD035J-MLW-AGN	12. Dez. 05	PS-LD0602-x-015	
Optrex	3,5	T-55343GD035JU-LW-AEN	8. Aug. 08	PS-LD0602-x-020	
Optrex	3,5	T-51963GD035J-MLW-AFN	21. Jul. 06	TBD	
Optrex	4,3	T-55226D043J-LW-A-AAN		TBD	
Optrex	5,0	T-55423GD050J-LW-A-AAN	9. Okt. 07	PS-LD0602-x-015	
Optrex	5,0	T-55423GD050J-LW-A-ABN	11. Dez. 07	PS-LD0602-x-015	
Optrex	5,0	T-55382GD050JU-LW-A-AAN	22. Aug. 07	PS-LD0602-x-015	
Optrex	5,0	T-55382GD050JU-LW-A-ABN	27. Okt. 07	PS-LD0602-x-015	
Optrex	5,7	T-55265GD057J-LW-ADN	23. Jul. 10	PS-LD0801-01*	
Optrex	5,7	T-55548GD057JU-LW-AAN	20. Nov. 09	PS-LD0301-044	
Optrex	5,7	T-55548GD057JU-LW-ABN	6. Jul. 10	PS-LD0301-044	
Optrex	5,7	T-55620GD057JU-LW-AAN	5. Nov. 10	PS-LD0301-044	
Optrex	6,5	T-55465D065J-LW-A-AAN	28. Apr. 08	PS-LD0301-038	14
Optrex	6,5	T-55465D065J-LW-A-ABN	16. Jun. 08	PS-LD0301-038	14
Optrex	6,5	T-55629D065J-LW-A-AAN	22. Mrz. 10	PS-LD0301-038	14
Optrex	6,5	T-51750GD065J-LW-AKN	26. Nov. 07	PS-LD0602-023	
Optrex	6,5	T-51750GD065J-LW-AON	24. Okt. 08	PS-LD0602-023	
Optrex	8,4	T-55466D084J-LW-A-AAN	28. Nov. 09	PS-LD0301-029	14
Optrex	8,4	T-55467D084J-LW-A-AAN	28. Nov. 08	PS-LD0301-029	14
Optrex	8,4	T-55549D084J-LW-A-AAN	28. Jan. 09	PS-LD0301-029	14
Optrex	8,4	T-55549D084J-LW-A-ACN	29. Mrz. 11	TBD	14
Optrex	9,0	T-55561D090J-LW-A-AAN	16. Jun. 09	PS-LD0301-039	14
Optrex	9,0	T-55561D090J-LW-A-ABN	29. Jun. 09	PS-LD0301-039	14
Optrex	9,0	T-55562D090J-LW-A-AAN	16. Jun. 09	PS-LD0801-01*	18
Optrex	9,0	T-55562D090J-LW-A-ABN	29. Jun. 09	PS-LD0801-01*	18

Optrex	10,4	T-55532D104J-LW-A-AAN	27. Feb. 09	PS-LD0301-039	14
Optrex	10,4	T-55532D104J-LW-A-ABN	9. Mai. 09	PS-LD0301-039	14
Optrex	10,4	T-55532D104J-LW-A-ADN	2. Jun. 09	PS-LD0401-x-080	17
Optrex	10,4	T-55533D104J-LW-A-AAN	13. Mrz. 09	PS-LD0301-039	14
Optrex	10,4	T-55533D104J-LW-A-ABN	22. Okt. 09	PS-LD0401-x-070	17
Optrex	10,4	T-55563D104J-LW-A-AAN	15. Jun. 09	PS-LD0801-01*	
Optrex	10,4	T-55563D104J-LW-A-ABN	12. Jun. 09	PS-LD0401-x-080	17
Optrex	12,1	T-55373D121J-LW-A-AAN	18. Jul. 08	PS-LD0301-032	14
Optrex	12,1	T-55374D121J-LW-A-AAN	18. Jul. 08	PS-LD0301-032	14
Optrex	12,1	T-55513D121J-LW-A-AAN	8. Jan. 09	PS-LD0301-032	14
Optrex	12,1	T-55566D121J-LW-A-AAN	31. Aug. 09	PS-LD0401-x-120	17
Optrex	14,1	T-55313D141J-LW-A-AGN	24. Jun. 10	TBD	19
Optrex	15,0	T-55519D150J-LW-A-AAN	20. Nov. 09	PS-LD0401-x-120	17
Optrex	15,0	T-55519D150J-LW-A-ABN	9. Nov. 09	TBD	
Optrex	15,0	T-55534D150J-LW-A-AAN	29. Jan. 09	PS-LD0401-x-120	17
Optrex	15,0	T-55534D150J-LW-A-ABN	6. Feb. 09	2xPS-LD0401-x-100	17
Optrex	17,5	T-55621D175J-LW-A-AAN	29. Jan. 10	PS-LD0401-x-120	17
Powertip	3,5	PH320240T-004-IC-1Q	5. Jul. 06	PS-LD0602-x-020	
Powertip	4,3	PH480272T-001-1A0Q	12. Mrz. 07	PS-LD0602-x-020	
Powertip	5,0	PH320240T-005-I-Q	4. Sep. 06	PS-LD0101-x-060	
Powertip	5,7	PH320240T-009-IC-1Q	19. Apr. 07	PS-LD0602-x-025	1
Prime View	3,5	PD035VL1	23. Nov. 07	PS-LD0101-X-040	
PrimeView	3,5	PD035VX2	21. Nov. 07	PS-LD0101-X-040	
PrimeView	3,5	PD035VX3	25. Dez. 07	PS-LD0101-x-040	
PrimeView	5,0	PD050VL1	24. Mrz. 08	PS-LD0101-x-160	10
PrimeView	5,7	PD057VT1	7. Jun. 07	PS-LD0101-x-240	
PrimeView	5,7	PD057VU7	24. Jul. 07	PS-LD0101-x-240	
PrimeView	6,4	PD064VT8 (2 LED Stränge)	8. Jan. 08	PS-LD0101-x-140	10
Prime View	7,0	PM070WL4	24. Mrz. 08	PS-LD0101-x-220	10
Prime View	7,0	PM070WM2	18. Sep. 09	PS-LD0101-x-180	10
PrimeView	7,0	PM070WT2	24. Mrz. 08	PS-LD0101-x-220	10
PrimeView	7,0	PM070WT3	24. Mrz. 08	PS-LD0101-x-220	10
PrimeView	7,0	PM070WX5	22. Dez. 06	PS-LD0101-x-220	10
PrimeView	7,0	PM070WX9	16. Nov. 07	TBD	
PrimeView	7,0	PM070WXF	26. Mrz. 08	TBD	
PrimeView	7,0	PM070WL4	22. Dez. 06	PS-LD0101-x-220	10
PrimeView	8,0	PD080SL02	24. Okt. 07	TBD	
Prime View	8,0	PD080SL2	24. Apr. 08	TBD	
Prime View	8,0	PD080SL3	25. Feb. 08	PS-LD0101-X-280	10
PrimeView	10,4	PD104SLF	24. Okt. 07	PS-LD0101-x-260	10
PrimeView	10,4	PD104SLG	20. Aug. 08	TBD	
PrimeView	12,1	PD121XL4	18. Jul. 08	TBD	10
Promate	15,0	90LM150X1MEA0F		voltage driven!	
Samsung	18,5	LTM185AT04	14. Sep. 10	PS-LD0401-x-yyy	
Seiko	4,3	RA158Z	15. Mai. 08	TBD	
Seiko	4,3	43WVF1G-0	22. Apr. 09	TBD	
Seiko	7,0	70WVW2AZ0	27. Jul. 09	PS-LD0801-01*	
Seiko	7,0	70WVW3T-0	31. Aug. 10	PS-LD0602-x-020	
Sharp	2,5	LQ025Q3DW02	7. Mrz. 08	PS-LD0602-x-020	
Sharp	3,5	LQ035Q1DH01	7. Mrz. 07	PS-LD0602-x-020	
Sharp	3,5	LQ035Q3DG01	24. Okt. 07	PS-LD0602-x-020	
Sharp	3,5	LQ035Q3DG03	8. Jul. 09	PS-LD0801-01*	
Sharp	3,5	LQ035Q3DW02	2. Sep. 08	PS-LD0602-x-020	
Sharp	3,5	LQ035Q7DB03F	11. Jul. 09	PS-LD0602-x-015	
Sharp	3,5	LQ035Q7DB05	4. Dez. 08	PS-LD0602-x-020	
Sharp	3,5	LQ035Q7DH03	7. Okt. 05	PS-LD0602-x-020	

Sharp	3,5	LQ035Q7DH06	29. Mai. 06	PS-LD0602-x-020	
Sharp	3,8	LQ038Q3DC01	23. Aug. 06	PS-LD0602-x-010	
Sharp	4,3	LQ043T1DG01	21. Jul. 06	PS-LD0602-x-020	
Sharp	4,3	LQ043T1DG02	26. Sep. 06	PS-LD0602-x-020	
Sharp	4,3	LQ043T3DG04	3. Okt. 08	PS-LD0801-01*	
Sharp	4,3	LQ043T3DX0A	26. Jul. 06	PS-LD0602-x-023	
Sharp	4,3	LQ043T3DX02	15. Mai. 07	PS-LD0602-x-018	
Sharp	4,3	LQ043T3DX04	15. Mai. 07	PS-LD0602-x-018	
Sharp	5,7	LQ057Q3DG01	14. Jan. 09	PS-LD0602-021-B	
Sharp	5,7	LQ057Q3DG02	15. Jun. 09	PS-LD0602-021-B	
Sharp	5,7	LQ057V3DG02	12. Sep. 07	internal control!	
Sharp	7,0	LQ070Y3LG1C	17. Okt. 08	PS-LD0301-028-B	(7)
Sharp	7,0	LQ070Y3LG4A	10. Jul. 09	PS-LD0602-x-020	
Sharp	7,0	LQ070Y3LW01	24. Jun. 09	PS-LD0801-01*	
Sharp	7,0	LQ070Y3DG3A	17. Feb. 09	PS-LD0602-x-020	
Sharp	7,0	LQ070Y3DG3B	11. Mrz. 09	PS-LD0602-x-020	
Sharp	8,4	LQ084V3DG02	12. Jul. 08	PS-LD0301-027-B	9
Sharp	10,4	LQ104S1DG34	8. Mai. 09	PS-LD0602-x-018	
Sharp	10,4	LQ104V1DG62	7. Feb. 08	CE-1077	
Sharp	10,4	LQ104V1DG62	7. Feb. 08	PS-LD0301-x	3 / 6
Sharp	10,4	LQ104V1DG62	19. Sep. 07	PS-LD0301-x	3 / 6
Sharp	10,4	LQ104V1DG62	10. Jul. 07	2x PS-LD0101-x-130	-
Sharp	10,6	LQ106K1LA05	1. Aug. 07	PS-LD0602-x-017	
Sharp	12,1	LQ121S1DC71	21. Okt. 10		
Sharp	12,1	LQ121S1LG62	9. Dez. 08	PS-LD0301-020-B	7
Sharp	12,1	LQ121S1LG63	10. Dec. 08	PS-LD0301-020-B	7
Sharp	12,1	LQ121X3LG02	18. Nov. 09	PS-LD0609-049	
Sharp	12,1	LQ121S1LG71	25. Dez. 09	internal control!	
Sharp	12,1	LQ121S1LG81	6. Apr. 10	internal control!	
Sharp	12,1	LQ121X3LGxx	18. Nov. 09	TBD	
Sharp	12,1	LQ121T3LW01	3. Dez. 09	internal control!	
Sharp	15,0	LQ150X1LG82	12. Jul. 09	PS-LD0304-x	7
Sharp	15,0	LQ150X1LG91	11. Dez. 09	internal control!	
Sharp	15,6	LQ156T1LGN1	28. Okt. 10	TBD	
Sharp	18,5	LQ185T1LGN3	29. Jan. 10	TBD	
Sharp	19,0	LQ190E1LW52	19. Mai. 11	PS-LD1601-01	
Sharp	19,0	LQ190E1LX51	12. Mrz. 10	internal control!	
Sharp	21,5	LQ215M1LGN2	29. Jan. 10	PS-LD0608-01	
Sharp	40,0	LK400D3LB43	25. Aug. 10	TBD	
Sharp	46,0	LK460D3LB33	19. Nov. 10	TBD	
Tianma	10,4	TM104SBH01	16. Dez. 09	PS-LD0101-x-120	10
Tianma	10,4	TM104SDH01	28. Nov. 08	PS-LD0101-x-120	10
Tianma	7,0	TM070RBH10	23. Aug. 10	PS-LD0101-x-160	
Tianma	15,6	TMS156WX1-12TB	9. Mrz. 11	PS-LD0401-1-060	
Tianma	19,0	TM190MDS01-00	4. Mrz. 11	PS-LD0401-1-060	
Toshiba	5,0	LTA050B352A		TBD	
Toshiba	5,7	LTA057A340F	1. Aug. 07	PS-LD0602-x-015	
Toshiba	5,7	LTA057A340F	2. Nov. 06	PS-LD0602-x-015	
Toshiba	6,5	LTA065B0D2F-V08R	3. Jul. 08	internal control!	
Toshiba	7,0	LT070AC46000	22. Mai. 08	PS-LD0602-x-015	
Toshiba	7,0	LT070AC46100	20. Aug. 09	PS-LD0602-x-015	
Toshiba	8,4	LTA084C271F-V04R	8. Apr. 08	internal control!	
Toshiba	8,4	LTA084C271F-V07R	3. Jul. 08	internal control!	
Toshiba	8,9	LTD089EXWS		TBD	
Toshiba	10,4	LTA104AD18900-V01R	16. Sep. 08	internal control!	
Toshiba	10,4	LTA104AC36100-V04R	24. Jun. 08	internal control!	

Toshiba	12,1	LT121AC33T00	2. Apr. 09	TBD	
Toshiba	12,1	LTD121EDFS	17. Jan. 07	PS-LD0801-01*	
Toshiba	12,1	LT121AC25500	12. Jun. 09	PS-LD0301-x	
Truly	4,8	TFT800480-30-E	29. Apr. 09	PS-LD0602-x-015	
URT	5,7	UMSH-7763JD-2F	21. Mai. 07	PS-LD0101-x-100	
URT	5,7	UMSH-8089MD-1T	3. Mrz. 09	internal control!	
URT	7,0	UMSH-8013MD-2T	22. Okt. 07	PS-LD0101-X-100	10
URT	7,0	UMSH-8050MD-T	5. Jun. 07	PS-LD0602-x-020	
URT	7,0	UMSH-8173MD-1T	15. Aug. 08	PS-LD0101-x-210	10
Winstar	3,5	WF35DTIACDA	1. Mai. 08	PS-LD0602-x-020	

***Please regard the maximum output power per string!**

Power Systems - The Power Solution

Address: Hauptstr. 48 ; 74360 Ilsfeld-Auenstein / Germany

Tel.: + 49 / 70 62 / 67 59 - 6

Fax: + 49 / 70 62 / 67 59 - 800

Web: www.Power-Systems.de

Email: Info@Power-Systems.de

10th November 2011

